



January 11 1888  
I commenced Survey of Section  
31 Town 7 North,  
Range 5 West.  
W. M. Clouston  
County Surveyor.

COURSE.	DISTANCE.	REMARKS.
East	41.34	From S W
	80.34	to S E
North	41.21 1/2	From S E
	82.43	to A E
West	40.00	From A E
	81.23	to A W
North	82.43	From S W
		to A W
West	40.05	From E 1/4
	81.40	to W 1/4

Corners Established.	Monument.	Bearing Trees.	Diameter in Inches.	Course.	Links Distant.
Re est S W		B Oak	20	A 40 E	19
		" "	24	S 11 1/2 E	32
		" "	15	S 62 E	72
S E	Large Stone	Stone Bench Mark for Town Mill ditch		A 41 E	74
A E	Stone already set	Double B. Oak	24	S 47 E	39
A W		W Oak	12	S 64 1/2 E	78 1/2
		Double W Oak	12	A 41 E	111
A 1/4 A W 1/4	Stone	Jack Oak	6	A 12 1/2 E	60
		Oak	4	S 56 E	160
A 1/4	Stone	Water Oak	18	S 57 1/2 W	70 43
E 1/4	Stone	Post Oak	24	A 70 1/2 W	83 1/4 S
		W Oak	12	A 4 W	61
S 1/4 A W 1/4	Stone	Beach Oak	5	A 77 E	22 1/4 43
E 1/4 A E		B Oak	12	A 14 W	29 1/2
		" Oak	15	S 15 E	63
E 1/4 S E	Stone	Elm	10	A 83 1/4 W	233 1/4 43
W 1/4	Stone	W Oak	24	A 49 E	82 1/2 1/4 S
W 1/4 S E 1/4	Stone				1/4 43
W 1/4 A W 1/4	Stone				1/4 43
S 1/4	Stone already set	Gum	10	A 15 1/2 E	44 1/2
		W Oak	6	S 66 E	56 1/2
S 1/4 S W 1/4	Stone				1/4 43
E 1/4 A E	"	B Oak	12	A 14 W	29 1/2
		" "	15	S 15 E	63
cen A W	Stone				1/4 43